

Homing in torque mode

For drives IMD / IMDL / IMDC series

NOTICE

Principle for carrying out homing at torque

1. Limit engine torque
2. Increase the maximum following error parameter
3. Start a move in the desired direction, at low speed
4. Wait until the following error increases and reaches a threshold
5. Reset the position of the axis
6. Disable the axis
7. Reset the initial motor torque values and the following error parameter
8. Revalidate the axis

Example

Settings :

- Nominal current= 2,1A
- Maximal current = 200%
- Nominal torque = 2,5Nm
Hence a maximum torque of 5Nm (2,5N x 200%)
It is desired to limit the torque to 0.63 N during the homing, 12.6% of the maximum torque
- Following error = 2 mm
- Float accuracy = 0,01 (on Options menu\Language iDPL\Compiler)

Program :

Task 1

Prog

...

...

Run 4 'Starts homing mode on torque

Wait Status(4) = 0 'wait homing done

Vel% = 100

...

...

EndProg

Task 4

Prog

' Storing initial following error

VL255 = ReadParam(60FBh,04h)

' Forcing error to 10,00 mm (unit linked to the float accuracy parameter)

WriteParam(60FBh,04h) = 1000

' Storing initial torque limitation

VL254 = ReadParam(60F6h,10h)

' Forcing limitation to 12,6 % of maximal torque (fixed unit expressed in 0,1%)

WriteParam(60F6h,10h) = 126

' Launching a low speed movement

Vel% = 3

Stti -

' Waiting for the following error threshold (ex : 5 mm)

BOUCLE:

VR250 = Fe_S

If VR250 < 0 Then

VR250 = -VR250

EndIf

If VR250 < 5 Goto BOUCLE ' threshold of 5 mm

' Resetting the axis position and disable

Home(0)

Axis Off

Delay 500

' Restore initial following error

WriteParam(60FBh,04h) = VL255

' Restore initial limitation torque

WriteParam(60F6h,10h) = VL254

' Enable

Axis On

Halt 4

EndProg

