
MD DRIVE SOLUTIONS for machine manufacturers

1 MD drive and PLC




2 MD drive and MMI




3 MD drive and PLC terminal

3.1 Single axis:




3.2 Multi axes:




A solution 3 axes optimized

4 MD drive connected with a PC



5 MD drive, PLC and MMI



Complex and powerful configuration

High I/O quantity